FloPlast

building the future

Step by step installation guide - Strap on Boss (SP319)



Cut a 54mm hole into the soil pipe.



Solvent weld around the hole and the flange of the Strap on Boss.



The Strap on Boss has a built in fall of 21/2 degrees. The word 'top' is embossed on the fitting to show the correct way up.



Push fittings together to secure bond.



Squeeze the clips at the back together to secure the Strap on Boss to the soil pipe.



For Push-Fit 32/40/50mm connections to pipe, use rubber boss adaptors SP10/11/12.



For Solvent Weld 32/40/50mm connections, use solvent weld adaptors SP20/21/22. Solvent cement fittings together to secure bond.



Roofline, Window and **Cladding Systems**



Systems





Underground Drainage



Systems

