

1. Apply the tape around the window or door to be glazed and press the film onto it.



3. Trim off the surplus film around the edges with a sharp knife.



2. Using a domestic hairdryer, warm the film and the creases will disappear.



4. Now enjoy all the comfort and heat saving of Wickes seasonal glazing film.